



Technical data

		Material	
Main product component	C9-12 isoparafin		
Property	Regulation	Value	
Characteristics		odourless	
Storage		cool and dry	
Packaging		can	

Areas of application

Apply pro clima GLUMEX to the surface to be cleaned with a soft cloth and gently rub it in. After just a few minutes, the contaminant can be seen coming away from the surface. The contaminant can then be rubbed off using a rough material (e.g. steel wool or a brush). If any residues remain, this process can be repeated.

It is recommended to test the compatibility of GLUMEX with the surface to be treated on a non-visible area of the surface.

Supply forms

Art. no.	GTIN	Contents	Weight	Sales unit	Container
10161	4026639017185	0.4	0.575 kg	3	501

Advantages



Removes adhesive residues left behind by adhesive tapes and acrylate copolymers





The information provided here is based on practical experience and the current state of knowledge. We reserve the right to make changes to the recommended designs and processing or to make alterations due to technical developments and associated improvements in the quality of our products. We would be happy to inform you of the current technical state of the art at the time you use our products.

Further information about installation and design details is available in the pro clima planning documentation. If you have any questions, please contact [pro clima Technical Support](https://proclima.com/ service/technical-support).

bauökologische Produkte GmbH

Rheintalstraße 35 - 43 D-68723 Schwetzingen Phone: +49 (0) 62 02 - 27 82.0 E-mail: info@proclima.com

