

GLUMEX

Adhesive remover



Technical data

Material	
Main component	C9-12 isoparaffin

Property	Regulation	Value
Storage		Cool and dry
Packaging		can
Odour		odourless

Areas of application

Apply pro clima GLUMEX to the surface to be cleaned with a soft cloth and gently rub it in. After just a few minutes, the contaminant can be seen coming away from the surface. The contaminant can then be rubbed off using a rough material (e.g. steel wool or a brush). If any residues remain, this process can be repeated.

It is recommended to test the compatibility of GLUMEX with the surface to be treated on a non-visible area of the surface.

Supply forms

Art. no.	GTIN	Contents	Weight	Sales unit	Container
10161	4026639017185	0.4 l	0.575 kg	3	501

Advantages

- ✓ Removes adhesive residues left behind by adhesive tapes and acrylate copolymers
- ✓ Highly effective within minutes



The information provided here is based on practical experience and the current state of knowledge. We reserve the right to make changes to the recommended designs and processing or to make alterations due to technical developments and associated improvements in the quality of our products. We would be happy to inform you of the current technical state of the art at the time you use our products.

Further information about installation and design details is available in the pro clima planning documentation. If you have any questions, please contact [pro clima Technical Support](<https://proclima.com/service/technical-support>).

MOLL

bauökologische Produkte GmbH
Rheinthalstraße 35 - 43
D-68723 Schwetzingen
Fon: +49 (0) 62 02 - 27 82.0
eMail: info@proclima.de